

# Road Committee Report

3/11/2019 thru 4/13/2019

## Section 1 & 2

### Road Work Completed

Panther Run from Ledge Road to End

- Dozer Blade, Crush and Water as needed

Worked Main Road from 166 to Tomahawk

- Blade wash-boarding and Water as needed
- Hauled 2 more loads of clay to mix with gravels

Repairs to Colleen and Stagecoach

- Blend sand mix to muddy sections
- Crush, Build crown and Water

Worked upper Cochise Canyon

- Dozer Blade, Crush and Fix knock-outs
- Hauled 6 loads of road mix to rocky sections

Worked Cochise Canyon from Stagecoach to High Meadow

- Blade and Crush, Reclaimed knock-out materials
- Hauled 3 loads of screen roll-off to crush as needed

Worked High Meadow from Cochise to 113 High Meadow

- Dozer Blade to fix side drainages, Rock removal
- Hauled 4 loads of mix to crush with native materials
- Build crown, Water as needed

### Equipment Repairs & Maintenance

Rock Crusher

- Replaced 2 belts
- Cleaned pulleys and adjusted transmission tension

Dozer

- Replaced 2 batteries
- Cleaned mounting brackets and added padding

Water Truck

- Replaced headlamp and adjusting screws
- Installed new air filter

Backhoe

- Oil and Filter change, New Air and Fuel filters
- Check all fluids and tire pressures
- Replaced 2 hydraulic hoses on steering pump

### Road Material Processing

- Excavated/Sifted 6 loads of pond materials from upper Duck Pond
- Excavated/Sifted 5 loads gravels from Limpia creek

### Additional Information

- Pushed up brush pile
- Repairs to shop roll-up door. Wind blown off tracks
- Dozer and Rock crusher process is slow but much needed to repair road beds.
- Thank you for your patience, Darell Fellers

Sincerely Submitted,  
Janette Winters