

Road Committee Report

03/20/2023 thru 04/08/2023

Road Work and Repairs

Section 1:

Worked 315 Colleen Canyon

- Placed 3 loads of rubble fill to build up washed out road edge

Section 2:

Worked Low Meadow with Dozer from 315 Low Meadow to High Meadow

- Removed pine tree at intersection to widen the turning radius at Skyline

Worked Skyline from Low Meadow to the turn-around

- Dozer work to rebuild the road bed
- Rock hammer work to break up all exposed embedded rocks
- Haul and placed 5 loads of road mix to build back washed out sections
- Trimmed limbs as needed, hauled 3 loads of limbs to the burn pile
- Placed 4 loads of water as needed to set road bed work

Section 1:

Scheduled work to continue on upper Colleen Canyon next week

- Rock hammer to be relocated for embedded rock removal
- Several loads of materials are required to build up the creek crossings

Requests to work Tomahawk and the Ranch Road will be addressed

Equipment Repairs & Maintenance

580K Backhoe

- Serviced front loader bucket control valves, cleaned out debris causing binding

410G Backhoe

- Replaced worn rock hammer bit with spare
- Will machine and resurface the chisel face for future use

Mack Dump

- Replaced right rear tire with used spare, loss of tire tread
- Replaced right front air brake hose assembly
- Power steering pump hoses need to be replaced, excessive leaking on low pressure side

Material Screen

- Welded upper frame corners with additional metal supports, added two screen brackets

Road Material Processing

- Excavated and hauled 14 loads of donated creek bed materials to the staging area
- Processed 11 loads or 145 cubic yards of road mix
- 120 cubic yards of caliche were delivered to the community center

Additional Information

- Pushed up Brush Pile as needed
- Installed new shut-off valve and filter on the fourth fuel tank for more storage capacity
- Off-road diesel and unleaded fuels were delivered

Sincerely Submitted, Road Committee Chairman and Crew