

Road Committee Report

1/15/2018 Thru 2/10/2018

Finishing Section 2

Skyline: Dozer work & Haul 5+ loads of road mix

502 Limpia Canyon Trail: Haul 1 load of road mix

Low Meadow: Haul 2 loads of road mix

High Meadow: Build 3 Water diversion berms

Starting Section 3

Tejano Trail: Cut road bed crown, Build water diversions, Haul road mix to rough spots

Juniper Pass & Trail: Blade Pass and Check knockouts on Trail

Calvary Court: Blade as needed, May need 1+ loads of road mix

McGuire Ridge: Blade as needed, May need 1 load of road mix

Tejano Canyon: Blade as needed

West Yellow Knife Trail & Court: Install culverts at water crossing and diversion berms on Court

Crazy Horse Trail & Loop: The Loop is in good condition, Trail needs work

East Yellow Knife Trail: Blade and Haul materials to cover rocky road bed

Tejas Run: Blade and Haul materials to rough spots

Tomahawk Trail to West Yellow Knife Trail: Blade & Fill in low spots in road bed

Winchester Pass: Clean water knockouts

Pinon Road: Still in good shape

McDonald Ridge: Needs a quick blade

Arrowhead Pass: Haul 2 loads of road mix

Road Work:

106 to 111 High Meadow, Haul and Set 4 loads of road mix, Cut knockouts as needed

111 to 114 High Meadow, Haul and Set 5 loads of road fill to adjust pitch, 2 loads of road mix to cover fill at switch backs

113 High Meadow, Work switch backs with dozer to establish road bed crown for better water control and diversion

206 to 306 Limpia Canyon, Remove large rocks, Haul & Set 2 loads of road mix, Built 3 water diversion berms

306 to 502 Limpia Canyon, Haul & Set 6 loads of road mix, Water as needed, Cut knockouts, Flagged trees for brush pile

Limpia Canyon Touch-Ups, Haul & Set 2 loads of road mix, Built 2 water diversion berms, Water to set road bed

Tony's Pass, Widen road bed, Removed large rocks, Watered as needed to set

206 to 215 High Meadow, Haul & Set 2 loads of road fill, Haul & Set 5 loads of road mix, Crown, 4 loads of water

Equipment Repairs:

Remove and Inspect PTO sensor on John Deere, Clean and Exercise PTO Switch, Check for loose connectors, PTO now works

Check for wear on male quick-disconnect couplings on John Deere, Replaced male couplings

Re-install shim board on water truck, Add additional metal shim spacer to support water tank on chassis

Replaced tire on maintainer, Installed new on the right middle position and rotated to right front, Send spare in for o-ring seal

Maintainer repairs to right wheel spindle, Remove bolt, Clean out grease raceway with penetrating fluid and grease

Maintainer repairs to left side steering cylinder bracket, Mill & Weld retaining pin, Heat & Straighten bracket, Replaced hose

Maintainer repairs to "wheel lean" cylinder bearing, Clean out grease raceway with penetrating fluid, Installed 90 degree fitting

Replaced "blade extend" hydraulic hose with a used one, Adjusted the rotary bracket to make clearance for hose fitting

Replaced fraid right side blade lift hydraulic hose with new one

Install new hydraulic hoses on Rock Crusher to operate tail gate

Equipment Maintenance: