

Road Committee Report

2/11/2019 thru 3/09/2019

Section 1

Road Work Completed

Colleen Canyon Repairs after rain storm

- Blade to clear off muddy sections

Stagecoach Pass Repairs after rain storm

- Blade to clear off muddy sections

Worked Main Road from 166 to Tomahawk

- Blade and Water as needed
- Hauled 2 loads of clay to mix with gravels

Panther Run from Stagecoach to Ledge Road

- Blade, Crush and Water as needed
- Rebuilt road bed crown with Dozer

Equipment Repairs & Maintenance

Rock Crusher

- Fabricated new skid plates
- Fabricated and welded new plates for front shoes
- Ordered replacement bolts and nuts to adjust striker plate

JD 7420

- Replaced battery
- Troubleshoot broken wire on draft sensor

Mack Dump

- Troubleshoot and repair broken ABS wires
- Grease all points as needed

Water Dump

- Repairs to headlamp mounting frame

Road Material Processing

- Excavated 18 loads of sand and gravels from Limpia Creek
- Sifted Clay for road mix

Additional Information

- Pushed up brush pile
- Ordered Cement Mixer
- Sold F800 Dump Truck
- Replaced water float valve at High Meadow well
- Replaced faulty check valves on Dip Tank pump/Windmill
- Well test performance on Dip Tank pump, See report
- Thank you Bill Flanders for Well Report and Testing

Sincerely Submitted,
Janette Winters