

DMPOA, Inc.
Road Report 4-8-2017

Worked:

Worked main road, Tomahawk. Screened more material.

Equipment:

John Deere is down looks like fuel pump, install transmission in small dump truck works good now waiting for linkage to install. Roller is up and going again.