

Road Report

11-12-2016

Equipment repair/maintenance:

Replace hose on backhoe

Replace tie rod on dump truck

Change oil & filter on maintainer

Truck had a flat tire

Torque converter is on Bulldozer just need to finish plumbing.

Worked:

Stagecoach, main road, Cochise and Limpia also touch up a spot at High Lonesome and Squaw Valley.

Screen material

Project:

Identify an exposed rock area on main road right passed cattle guard and hauled in screened and mixed material. Grade, packed and watered. Did this on 10-26 / 10-27. Will evaluate this with time.