

580K Backhoe

- Installed new starter. Ordered new seals for valve covers and spare front wheel bolts

Dozer

- Pressure washed and serviced all fluids. Ordered new air filters, upper radiator mounting hardware and hoses, replaced missing belly pan bolts

Mack Dump

- Clutch throw-out bearing starting to bind. Pricing replacement bearing and clutch kit
- Welded tailgate retaining chains to control the placement of Caliche onto road ways

Road Material Processing

- Excavated and screened 9 loads of clay and fire ash from clay pond
- Excavated and screened 5 loads of reclaimed sand and gravels from Squaw Valley
- Placed and blended 35 cubic yards of Caliche, Approximately 85 cubic yards in stock

Additional Information

- Pushed up brush pile with Dozer, Bladed perimeter to widen useable space
- Placed and took delivery of 800 gallons of red Diesel fuel and 250 gallons of unleaded
- Repaired water leak on water supply to dip and stock tanks, coupling failure
- Working Bourassa Trail, Squaw Valley, Buckboard Pass, Saddle Bags, High Lonesome

Sincerely Submitted,
The Road Committee and Crew