

# Road Committee Report

3/12/2018 Thru 4/14/2018

## Working Section 4

Bandolero Trail  
Apache Trail  
Skull Rock Trail  
Six Shooter  
Broken Spoke  
Victoria Point  
Remington Ridge  
Chancelor Canyon

## Road Work Completed:

Main Road from 166 to Tomahawk cattle guard. Blade, Crush & Water. Three volunteer Flaggers assisted with traffic. Thank you.  
Tomahawk from cattle guard to Thompson Trail. Blade, Crush and Water. Removed large rocks from road sides.  
Tomahawk from Thompson Trail to Yellow Knife. Blade, Crush and Water.  
McDonald Ridge. Blade, Crush and Water.  
Tomahawk from West Yellow Knife to East Yellow Knife. Blade, Crush and Water. Blade and Smooth Road bed at Limpia Creek Crossing  
East Yellow Knife to Tejas. Blade and Hauled 2 loads of mix. Water to set.  
Tejas in good condition at this time.  
Apache Trail from Bandolero to Six Shooter. Blade, Crush and Water.  
West Yellow Knife to Crazy Horse Loop. Blade and Hauled 2 loads of mix. Water to set.  
Yellow Knife Court. Blade and Hauled 1 load of mix. Water to set.  
Crazy Horse Loop to West Yellow Knife. Blade, Crush and Water. Reclaim materials from water knockouts.  
Winchester Pass from Tomahawk to Bandolero. Shuttle reclaimed materials to smooth creek crossing  
116 Skyline to 124 Skyline. Blade and Hauled 2 loads of mix.  
Tomahawk at Church Hill. Blade and Haul 2 loads of mix. Water to set.  
Bandolero from Tomahawk to Winchester Pass. Blade and Hauled 1 load of mix. Water to set.

## Equipment Repairs:

Welded Circle Frame hairline fracture on Maintainer  
Replaced Hydraulic Pump and Coupling on Backhoe  
Replaced Engine mounts, 2 rear and 2 front on Backhoe  
Replaced leaking air line to tail gate release cylinder  
Tear down front axle on John Deere to replace pivot bushings and Universal Bearings

## Equipment Maintenance:

Grease equipment and maintain fluid levels  
Wash equipment to keep clean and monitor any leaks  
Fueled and Exercised welder in both low and high idle modes.

## Personnel Training:

Demonstrate Maintainer controls and operations to start and drive equipment

## Road Material Processing:

Ray excavated and hauled 4 loads of sand & gravel from Limpia Creek  
Ray hauled 1 load of silty pond dirt  
Ray sifted 5 loads materials to process road mix  
Purchased 54 cubic yards of Caliche. Piled for inventory  
Current Inventory: Road Mix- 10 cubic yards, Clay- 5 cubic yards, Sand/Gravels- 5 cubic yards, Caliche- 100 plus cubic yards

## Additional Information:

Mr. Woffard assisted in the drilling of new sign post holes. Thank you  
Julian & Willis set sign posts in concrete. Thank you

New metal workbench fabricated and installed in the shop. Thank you Julian and Sam.

Organized shop work space and inventory items on shelves.

Monitor and Maintain water levels at High Meadow Tank and Community Center Dip Tank

A complaint came in regarding placing culverts on West Yellow Knife. The complaint was that the previous culverts washed away. After speaking with Jerry Rhea, he stated there have never been culverts in that area. The Road Committee will meet and consider the placement of the culverts.

The new culverts that were purchased were not purchased with DMPOA funds. There was a fundraiser for this project. No DMPOA fund were used.

**Extreme Dry Conditions make for Loose Road Beds**

**Please Drive with Care**

Respectfully Submitted,

Jackie Edwards, Road Committee Chairman

Cindy Davis, Road Committee Member